



# **POLAROID T-REX PLUS**

## **Flat Bed Large Format Printer**


### **SITE PREPARATION**





**Machine Size:**  
Area≈13 m<sup>2</sup>

**Electricity Request**




**Power: 4800W 25A –**  
**Requirements: AC220 Single-Phase 50/60Hz**






Electricity Standard:



## Electricity Standard:



Ps. The current that we write here is the Rated current

## Preparation For Installation:

1. Computer + computer monitor



System: win10 64bits  
 CPU: >1GHZ USB:2.0/3.0  
 Hardware: >500G RAM:>4GB  
 Resolution: >1024\*768  
 10th generation core i7  
 processor onwards  
 16gb RAM

2. Forklift



Weight  
 Printer: Around 1500KG  
 Package: Around 2000KG  
 Size  
 Printer: 4760mm(L)\*2096mm(W)\*1592mm(H)  
 Package:  
 5000mm(L)\*2260mm(W)\*1900mm(H)  
 Suggest rated load:3000KG  
 Suggest fork Arm: >1600MM



### 3. Toolkit

As our technician can't take toolkit for oversea trip.  
In order to make sure everything goes well, please prepare some conventional tools.



or



# polaroid

**Calle 10 No. 206, Col. Granjas San Antonio  
Del. Iztapalapa, C.P. 09070  
CDMX, México**

**info@equipamientos.mx  
www.equipamientos-polaroid.com**

